

1



2



3



4



5



6



6



7



7




7



8



8



8



8



9



9



10



10



10



11



12




12



13



14



14



15



Comments:

Dørstop defekt Venstre fordør
Stenslag kølerhjel
Stenslag forrude

Udstyr: